



Environmentally Friendly Solutions For Industry

**A 350MW POWER STATION CONDENSER BEFORE AND AFTER TREATMENT**



02.20.08

**U1 Inspection before cleaning**

Barnacles at bottom corner



05.24.08

**U1 Inspection after cleaning**

No barnacles at same spot




Environmentally Friendly Solutions For Industry



02.20.08

**Inspection before cleaning**



05.24.08

**Inspection after cleaning**

No fouling



Environmentally Friendly Solutions For Industry



02.20.08

**Inspection before cleaning**  
U1 Condenser Inlet



06.14.08

**Inspection after cleaning**  
U1 Condenser Inlet

Much cleaner surface, no fouling