



Environmentally Friendly Solutions For Industry

A 350MW POWER STATION CONDENSER BEFORE AND AFTER TREATMENT



02.20.08

U1 Inspection before cleaning

Barnacles at bottom corner



05.24.08

U1 Inspection after cleaning

No barnacles at same spot




Environmentally Friendly Solutions For Industry



02.20.08

Inspection before cleaning



05.24.08

Inspection after cleaning

No fouling



Environmentally Friendly Solutions For Industry



02.20.08

Inspection before cleaning
U1 Condenser Inlet



06.14.08

Inspection after cleaning
U1 Condenser Inlet

Much cleaner surface, no fouling